

## Diagnostic History

The Report is created by **LAUNCH X-431**

---

### Vehicle Information

License #:

Make:Mercedes-Benz

Model:167.119 - GLE 300 d 4MATIC

VIN:W1N1671191A281283

Odometer:69549 miles

Test Time:2025-01-18 02:00:13AM

Vehicle Software Version:V50.26

Diagnostic Application Version:V1.00.005

User Operation:Automatically Search

---

### DTC

<b>DTC</b>	<b>Description</b>	<b>State</b>	<b>System</b>
P1BC100	Additional fault freeze frame data for fault analysis (data set 01)_	STORED	ECM - Engine Control Module(CDI)
P2C7A09	The efficiency of SCR catalytic converter 2 (cylinder bank 1) is not sufficient.There is a component fault.	CURRENT and STORED	ECM - Engine Control Module(CDI)
U121887	Communication with actuator motor "Switchover valve of low-temperature circuit 1" has a malfunction.The message is missing.	CURRENT and STORED	PTCU - Control Unit 'Powertrain'
U121800	Communication with actuator motor "Switchover valve of low-temperature circuit 1" has a malfunction._	CURRENT and STORED	PTCU - Control Unit 'Powertrain'
B210F00	Input "Circuit 30" has a malfunction._	STORED	ES - Electrical Power Steering
B223292	PARKTRONIC has a malfunction.The function or the instruction is faulty.	STORED	PTS - PARKTRONIC
C174AFB	The learned value of an operating parameter of control unit "COLLISION PREVENTION ASSIST" is outside the valid range.The calibration of control unit "Active Brake Assist" has a malfunction./Active Distance Assist DISTRONIC_	STORED	SG-AWF - COLLISION PREVENTION ASSIST
U112787	Communication with one or more color generation and coupling modules on LIN bus 6 has a malfunction.The message is missing.	STORED	AML - Ambiance Light
U116000	A bus keepawake unit was detected._	CURRENT and STORED	EZS - Electronic Ignition Lock
B22A31C	Control unit "Overhead control panel" has a malfunction.The voltage value is outside the permissible range.	STORED	Driver-side SAM - Front Signal Acquisition And Actuation Module
B23267B	Fill level sensor "Washer fluid level" has a malfunction.The fluid level is too low.	CURRENT and STORED	Driver-side SAM - Front Signal Acquisition And Actuation Module
B11FA4B	Heater pad "Left front backrest" has a malfunction.There is a fault due to overtemperature.	STORED	REAR SAM - Rear Signal Acquisition And Actuation Module
B11FB4B	Heater pad "Left front seat cushion" has a malfunction.There is a fault due to overtemperature.	STORED	REAR SAM - Rear Signal Acquisition And Actuation Module
B23B513	The right rear brake wear sensor has a malfunction.There is an open circuit.	STORED	REAR SAM - Rear Signal Acquisition And Actuation Module

P1C5C00	Battery discharge protection is activated._	STORED	IC - Instrument Cluster
B211A01	The data line between the instrument cluster and the display cluster has a malfunction.There is a general electrical fault.	STORED	IC - Instrument Cluster
B173D15	The output for the turn signal lamp in the outside mirror has a malfunction.There is a short circuit to positive or an open circuit.	STORED	DCU-LF - Left Front Door
U121887	Communication with actuator motor "Switchover valve of low-temperature circuit 1" has a malfunction.The message is missing.	CURRENT	PTCU - Control Unit 'Powertrain'
U121800	Communication with actuator motor "Switchover valve of low-temperature circuit 1" has a malfunction._	CURRENT	PTCU - Control Unit 'Powertrain'