

FIN: W1N 167159 1A 590513

Current advice for the vehicle:

- ESKULAB request necessary due to special warranty















Outstanding KDM:

none

ESKULAB decisions:

none

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	12.07.2025		12	010200V28	Accident other (CAC only) primary & secondary benefits (CAC only)	00007F6A6	RO W	56922	36993	km	1	000001372	08.08.2025
	22.01.2025				Service minor - regelm. Wartung - BZ	70/Z/2025	559	09300	31477	km			
	12.06.2024		11	091901018	24P9190101	3506/G	559	09300	24144	km	1	000001071	14.06.2024
	27.03.2024		10	054942068	24P5494206	93092	559	07900	21916	km	1	000001060	29.03.2024
	30.08.2023		9	047902057	23P4790205	90296	559	07900	15828	km	1	000001032	15.09.2023
	30.08.2023		8	068119H27	Lid, center armrest/stowage compartment, front Locks up	90296	559	07900	15828	km	1	000001032	15.09.2023
	30.08.2023		7	08221SFZ8	Function, KEYLESS-GO, KEYLESS-START Does not open	90296	559	07900	15828	km	1	000001032	15.09.2023
	30.08.2023		6	05904Y747	K/Z*, control unit, rear switching module Contact fault/open circuit	90296	559	07900	15828	km	1	000001032	15.09.2023
	19.04.2023		5	059020747	K/Z*, coolant temperature sensor Contact fault/open circuit	88336	559	07900	12155	km	1	000001012	28.04.2023
	23.01.2023				Service minor - regelm. Wartung	424/Z/23	559	04400	10247	km			
	02.12.2022		4	074900018	22P7490001	86086	559	07900	9148	km	1	000000992	09.12.2022
	08.06.2022		3	069001367	Roof lining/headlining Noise	84187	559	07900	3176	km	1	000000975	12.08.2022
	03.02.2022		2	062N19767	Firewall, right, lower Seam sealant incomplete	84101	559	07900	540	km	1	000000974	05.08.2022
	15.12.2021		1	072D01**7	Side window, front door, left **	80527	559	07900	17	km	1	000000945	14.01.2022