

Diagnostic History

The Report is created by **LAUNCH X-431**

Vehicle Information

License #:

Make:Mercedes-Benz

Model:118.387 - CLA 200 Coupe

VIN:W1K5J8HB2PN351664

Odometer:33076 miles

Test Time:2026-03-02 09:27:47AM

Vehicle Software Version:V50.26

Diagnostic Application Version:V1.00.006

User Operation:Automatically Search

DTC

DTC	Description	State	System
P05AE77	Radiator shutter 2 does not close.The commanded position cannot be reached.	STORED	PTCU - Drivetrain
P05AE09	Radiator shutter 2 does not close.There is a component fault.	STORED	PTCU - Drivetrain
P054612	Temperature sensor 1 "Exhaust system" (cylinder bank 1) has a short circuit to positive.There is a short circuit to positive.	STORED	ME - Motor Electronics
P054622	Temperature sensor 1 "Exhaust system" (cylinder bank 1) has a short circuit to positive.The signal amplitude is greater than the maximum amplitude.	STORED	ME - Motor Electronics
B223209	PARKTRONIC has a malfunction.There is a component fault.	STORED	PTS - PARKTRONIC
U016787	Communication with the anti-theft alarm system has a malfunction.The message is missing.	STORED	Driver-side SAM - Front Signal Acquisition And Actuation Module
P1C5C00	Battery discharge protection is activated._	STORED	IC - Instrument Cluster