

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Vehicle Information

Make:Mercedes-Benz
Model:177.003 - A 180 d
VIN:W1K1770031J187442
Odometer:41402 miles
Vehicle Software Version:V50.26
Diagnostic Application Version:V1.00.006
Diagnostic path:177>177.003 - A 180 d>Health Report



Repair Shop

Shop Name:!
Address:
Zip Code:
Telephone:
Email:
SN:988684032318
Test Time:2025-06-24 06:06:58



System fault code 【Pre-Repair】

The following systems are OK:

- 1.PTCU - Drivetrain
- 2.ECM - Engine Control Module(CDI)
- 3.FSCU - Fuel Pump
- 4.SCR - Selective Catalytic Reduction
- 5.EZS - Electronic Ignition Lock
- 6.SG-SW-L - Left Headlamp
- 7.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 8.LIN: AISP - Dimming Inside Rearview Mirror
- 9.B95 (Battery sensor)
- 10.N70 (Overhead control panel control unit)
- 11.LIN: RGLS - Rain/Light Sensor
- 12.Windshield wiper
- 13.SG-SW-R - Right Headlamp
- 14.SRS - Supplemental Restraint System

15.N110 (Weight Sensing System (WSS) control unit)

16.SCM - Steering Column Module

17.LRE - Steering Wheel Electronics

18.ATA - Interior Motion Sensor

19.LIN: AS - Alarm Siren

20.Active Brake Assist

21.RFK - Backup Camera

22.MFK - Multifunction Camera

23.TPM - Tire Pressure Monitor

24.ES - Electrical Power Steering

25.ESP - Electronic Stability Program

26.ZAN - Audio/COMAND Display

27.Control Unit For Telematics Services

28.Audio - Audio Or COMAND

29.IC - Instrument Cluster

30.TPAD - Touchpad

31.AAC - Air Conditioning

32.DCU-LF - Left Front Door

33.N69/3 (Left rear door control unit)

34.DCU-RF - Right Front Door

35.N69/4 (Right rear door control unit)



Disclaimer

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!