

Inspection Report

This report is created by



Vehicle Information

VIN: VWWZZ3CZNE*****
Vehicle manufacturer/model: VW/
Year of manufacture: 2022
Mileage: 52834 miles
Vehicle Software Version: V29.00

Inspection Organization

Name: !
Address:
Contact Number: ☐
SN: 988684032318
Time and date of inspection: 10/21/2025 07:20:41



Inspection Result

Inspections are normal for Power system

1.01 Engine Electronics

Inspections are normal for Safety and Security system

1.03 Brake Electronics
2.13 Distance Regulation
3.15 Airbag
4.23 Brake Boost
5.2B Steering Column Lock
6.44 Power Steering
7.6C Rear View Camera System
8.76 Parking Aid
9.A5 Front Sensor For Drivers Assistant Systems

Inspections are normal for Vehicle body system

1.08 Climate Control Module
2.09 Electronic Central Electric
3.17 Instrument Cluster
4.19 Data Bus OBD Interface
5.42 Driver's Door Electronics
6.52 Passenger's Door Electronics
7.5F Information Electronics 1
8.B7 Interface For Access/Start System

Inspections are normal for Infotainment system

1.75 Emergency Call Module And Communication Unit

Professional Report

01 Engine Electronics	Normal
03 Brake Electronics	Normal
08 Climate Control Module	Normal
09 Electronic Central Electric	Normal
13 Distance Regulation	Normal
15 Airbag	Normal
17 Instrument Cluster	Normal
19 Data Bus OBD Interface	Normal
23 Brake Boost	Normal
2B Steering Column Lock	Normal
42 Driver's Door Electronics	Normal
44 Power Steering	Normal
52 Passenger's Door Electronics	Normal
5F Information Electronics 1	Normal
6C Rear View Camera System	Normal
75 Emergency Call Module And Communication Unit	Normal
76 Parking Aid	Normal
A5 Front Sensor For Drivers Assistant Systems	Normal
B7 Interface For Access/Start System	Normal

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.