

Inspection Report

This report is created by



Vehicle Information

VIN: W1N1671591A*****
 Vehicle manufacturer/model: Mercedes-Benz/167.159 - GLE 450 4MATIC
 Year of manufacture:
 Mileage: 24142 miles *Manual data entry
 Vehicle Software Version: V50.26

Inspection Organization

Name: 1
 Address:
 Contact Number:
 SN: 988684032318
 Time and date of inspection: 12/05/2025 13:43:56



Inspection Result

Inspections are normal for Power system

- 1.PTCU - Drivetrain
- 2.ECM - Engine Control Module(ME)
- 3.TCM - Transmission Control Module

Inspections are normal for Chassis system

- 1.TPM - Tire Pressure Monitor

Inspections are normal for Safety and Security system

- 1.SRS - Supplemental Restraint System
- 2.SCM - Steering Column Module
- 3.PTS - PARKTRONIC
- 4.ES - Electrical Power Steering
- 5.ESP - Electronic Stability Program

Inspections are normal for Vehicle body system

- 1.FSCU - Fuel Pump
- 2.48V - Starter-alternator
- 3.AML - Ambiance Light
- 4.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 5.LIN: AISP - Dimming Inside Rearview Mirror
- 6.B95 (Battery sensor)
- 7.N70 (Overhead control panel control unit)
- 8.LIN: RGLS - Rain/Light Sensor
- 9.Windshield wiper
- 10.REAR SAM - Rear Signal Acquisition And Actuation Module
- 11.Seat heater/seat ventilation
- 12.DDW - DC/DC Converter
- 13.G1/3 (48 V on-board electrical system battery)
- 14.EZS - Electronic Ignition Lock
- 15.N38 (Rear switching module)
- 16.SG-SW-L - Left Headlamp
- 17.SG-SW-R - Right Headlamp
- 18.N110 (Weight Sensing System (WSS) control unit)
- 19.RevETR-LF - Left Front Reversible Emergency Tensioning Retractor
- 20.RevETR-RF - Right Front Reversible Emergency Tensioning Retractor
- 21.SD - Sliding Roof/Panoramic Sliding Sunroof
- 22.LRE - Steering Wheel Electronics
- 23.ATA - Interior Motion Sensor
- 24.LIN: AS - Alarm Siren
- 25.SG-FAS - Mercedes-Benz Intelligent Drive
- 26.MFK - Multifunction Camera
- 27.Control Unit For Telematics Services
- 28.IC - Instrument Cluster
- 29.AC - Air Conditioning
- 30.DCU-LF - Left Front Door
- 31.DCU_RF - Right Front Door
- 32.DCU-LR - Left Rear Door
- 33.DCU-RR - Right Rear Door
- 34.HKS - Tailgate Control
- 35.ESA Driver - Electrical Seat Adjustment Driver
- 36.ESA Front Passenger - Electrical Seat Adjustment Front Passenger

Inspections are normal for Infotainment system

- 1.ZAN - Audio/COMAND Display
- 2.Audio - Audio Or COMAND
- 3.SOUND - Sound System
- 4.TPAD - Touchpad

Professional Report

PTCU - Drivetrain	Normal
FSCU - Fuel Pump	Normal
48V - Starter-alternator	Normal
ECM - Engine Control Module(ME)	Normal
TCM - Transmission Control Module	Normal
AML - Ambiance Light	Normal
Driver-side SAM - Front Signal Acquisition And Actuation Module	Normal
LIN: AISP - Dimming Inside Rearview Mirror	Normal
B95 (Battery sensor)	Normal
N70 (Overhead control panel control unit)	Normal
LIN: RGLS - Rain/Light Sensor	Normal
Windshield wiper	Normal
REAR SAM - Rear Signal Acquisition And Actuation Module	Normal
Seat heater/seat ventilation	Normal
DDW - DC/DC Converter	Normal
G1/3 (48 V on-board electrical system battery)	Normal
EZS - Electronic Ignition Lock	Normal
N38 (Rear switching module)	Normal
SG-SW-L - Left Headlamp	Normal
SG-SW-R - Right Headlamp	Normal
SRS - Supplemental Restraint System	Normal
N110 (Weight Sensing System (WSS) control unit)	Normal
RevETR-LF - Left Front Reversible Emergency Tensioning Retractor	Normal
RevETR-RF - Right Front Reversible Emergency Tensioning Retractor	Normal
SCM - Steering Column Module	Normal
SD - Sliding Roof/Panoramic Sliding Sunroof	Normal
LRE - Steering Wheel Electronics	Normal
ATA - Interior Motion Sensor	Normal
LIN: AS - Alarm Siren	Normal
SG-FAS - Mercedes-Benz Intelligent Drive	Normal
PTS - PARKTRONIC	Normal
MFK - Multifunction Camera	Normal
TPM - Tire Pressure Monitor	Normal
ES - Electrical Power Steering	Normal
ESP - Electronic Stability Program	Normal
ZAN - Audio/COMAND Display	Normal
Control Unit For Telematics Services	Normal
Audio - Audio Or COMAND	Normal
IC - Instrument Cluster	Normal
SOUND - Sound System	Normal
TPAD - Touchpad	Normal
AC - Air Conditioning	Normal
DCU-LF - Left Front Door	Normal
DCU_RF - Right Front Door	Normal
DCU-LR - Left Rear Door	Normal
DCU-RR - Right Rear Door	Normal
HKS - Tailgate Control	Normal
ESA Driver - Electrical Seat Adjustment Driver	Normal
ESA Front Passenger - Electrical Seat Adjustment Front Passenger	Normal

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.