

Inspection Report

This report is created by

LAUNCH X431**Vehicle Information**

VIN: WUAZZZF34M1*****
 Vehicle manufacturer/model: Audi/
 Year of manufacture: 2021
 Mileage: 62619 miles *Manual data entry
 Vehicle Software Version: V29.02

Inspection Organization

Name: I
 Address:
 Contact Number: 0
 SN: 988684032318
 Time and date of inspection: 02/12/2026 11:02:15

Inspection Result

There are 1 issues for Vehicle body system:

1.Navigation System - Navigation Database Malfunctioning

Inspections are normal for Power system

 1.01 Engine Electronics
 2.02 Transmission Electronics
 3.22 All-Wheel Drive Electronics

Inspections are normal for Safety and Security system

 1.03 Brake Electronics
 2.13 Distance Regulation
 3.14 Wheel Damping Electronics
 4.15 Airbag
 5.44 Power Steering
 6.6C Rear View Camera System
 7.76 Parking Aid
 8.A5 Front Sensor For Drivers Assistant Systems

Inspections are normal for Vehicle body system

 1.08 Climate Control Module
 2.09 Electronic Central Electric
 3.17 Instrument Cluster
 4.19 Data Bus OBD Interface
 5.42 Driver's Door Electronics
 6.4B Multi-Function Module
 7.52 Passenger's Door Electronics
 8.6D Rear Lid Electronics
 9.A9 Structure-Borne Sound Actuator
 10.B7 Interface For Access/Start System
 11.BB Rear Drivers Side Door Electronics
 12.BC Rear Passenger Side Door Electronics
 13.CA Sunroof Control Module
 14.D6 Light Control Left 2
 15.D7 Light Control Right 2
 16.DE Charging Device 1 For Mobile End Device

Inspections are normal for Infotainment system

1.75 Emergency Call Module And Communication Unit

Professional Report

01 Engine Electronics	Normal
02 Transmission Electronics	Normal
03 Brake Electronics	Normal
08 Climate Control Module	Normal
09 Electronic Central Electric	Normal
13 Distance Regulation	Normal
14 Wheel Damping Electronics	Normal
15 Airbag	Normal
17 Instrument Cluster	Normal
19 Data Bus OBD Interface	Normal
22 All-Wheel Drive Electronics	Normal
42 Driver's Door Electronics	Normal
44 Power Steering	Normal
4B Multi-Function Module	Normal
52 Passenger's Door Electronics	Normal
5F Information Electronics 1	Abnormal 1
6C Rear View Camera System	Normal
6D Rear Lid Electronics	Normal
75 Emergency Call Module And Communication Unit	Normal
76 Parking Aid	Normal
A5 Front Sensor For Drivers Assistant Systems	Normal
A9 Structure-Borne Sound Actuator	Normal
B7 Interface For Access/Start System	Normal
BB Rear Drivers Side Door Electronics	Normal
BC Rear Passenger Side Door Electronics	Normal
CA Sunroof Control Module	Normal
D6 Light Control Left 2	Normal
D7 Light Control Right 2	Normal
DE Charging Device 1 For Mobile End Device	Normal

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.